

WAC LIGHTING

Responsible Lighting®

Dimming Compatibility

ID E2008097V0

Product Family: Fitzgerald
Sku Tested: WS-47108
Related Models WS-47116

Test Voltage: 120V
Control Type: ELV/TRIAC

Test Notes: Refer to dimmer manufacturer's dimmer load rating for min and max fixture quantities per dimmer.

| Manufacturer | Product | Model Number | Test Voltage (V) | Measured Dimming Range | Comments |
|--------------------------------------|----------------------|---------------|------------------|------------------------|--------------------------------|
| | | | | Low End | |
| Adaptive Phase Dimmers | | | | | |
| Control4 | Adaptive | C4-APD120 | 120 | 3.0% | |
| Legrand | Adorne Touch (ELV) | ADTH700RMTUM1 | 120 | 2.0% | |
| Legrand | Adorne Touch (TRIAC) | ADTH700RMTUM1 | 120 | 4.0% | Not Recommended |
| Legrand | Radiant | RH703PTUW | 120 | 6.0% | |
| Legrand | Adorne (ELV) | ADTP703TUW4 | 120 | 5.0% | |
| Legrand | Adorne (TRIAC) | ADTP703TUW4 | 120 | 2.0% | Not Recommended |
| Cooper | AL Series | AAL06 | 120 | 2.0% | |
| Reverse Phase Dimmers (ELV) | | | | | |
| Lutron | Nova T | NTELV-600 | 120 | 2.0% | |
| Lutron | Diva | DVELV-300P | 120 | 3.0% | |
| Lutron | Maestro | MAELV-600 | 120 | 2.0% | |
| Lutron | Skylark | SELV-300P | 120 | 2.0% | |
| Leviton | Illumatech | IPE04-1LZ | 120 | 3.0% | |
| Lutron | Maestro | RRD-6NA | 120 | 3.0% | |
| Leviton | SureSlide | 6615-POW | 120 | 8.0% | |
| Leviton | Decora | DSE06-10Z | 120 | 2.0% | |
| Lutron | Caseta | PD-5NE | 120 | 2.0% | |
| Lutron | Homeworks | HRD-5NE | 120 | N/A | Flashing at high dimming level |
| Lutron | Homeworks | HQRD-6NA | 120 | 2.0% | |
| Leviton | Renoir II | AWSMT-EBW | 120 | 3.0% | |
| Lutron | Grafik-Eye | GRX-3103-A-G | 120 | 2.0% | |
| Forward Phase Dimmers (TRIAC) | | | | | |
| Lutron | Maestro | MACL-153M-WH | 120 | 2.0% | |
| Lutron | Diva | DVCL-153P | 120 | 12.0% | Flicker below 12% |
| Legrand | Adorne Paddle | ADPD453LW2 | 120 | 8.0% | Flicker below 8% |
| Lutron | Ariadni | AYCL-153PH | 120 | 2.0% | |
| Lutron | Skylark | SCL-153P-WH | 120 | 2.0% | |
| Lutron | Maestro | MA-600-WH | 120 | N/A | Dimmer not responsive |
| Leviton | SureSlide | 6674-POW | 120 | N/A | Flashing at high dimming level |
| Lutron | Caseta | PD-6WCL | 120 | N/A | Flashing at high dimming level |
| Legrand | Harmony | HCL453PW | 120 | 7.0% | Flicker below 7% |
| Legrand | Radiant | RHCL453PW | 120 | 16.0% | Flicker below 16% |

WAC LIGHTING

Responsible Lighting®

Dimming Compatibility

ID E2008098V0

Product Family: Fitzgerald
Sku Tested: WS-47116
Related Models WS-47108

Test Voltage: 120V
Control Type: ELV/TRIAC

Test Notes: Refer to dimmer manufacturer's dimmer load rating for min and max fixture quantities per dimmer.

| Manufacturer | Product | Model Number | Test Voltage (V) | Measured Dimming Range | Comments |
|--------------------------------------|----------------------|---------------|------------------|------------------------|--------------------------------|
| | | | | Low End | |
| Adaptive Phase Dimmers | | | | | |
| Control4 | Adaptive | C4-APD120 | 120 | 4.0% | |
| Legrand | Adorne Touch (ELV) | ADTH700RMTUM1 | 120 | 57.0% | Flashing at high dimming level |
| Legrand | Adorne Touch (TRIAC) | ADTH700RMTUM1 | 120 | 53.0% | Not Recommended |
| Legrand | Radiant | RH703PTUW | 120 | 11.0% | Flicker below 11% |
| Legrand | Adorne (ELV) | ADTP703TUW4 | 120 | 3.0% | |
| Legrand | Adorne (TRIAC) | ADTP703TUW4 | 120 | 13.0% | Not Recommended |
| Cooper | AL Series | AAL06 | 120 | 46.0% | Flashing at low dimming level |
| Reverse Phase Dimmers (ELV) | | | | | |
| Lutron | Nova T | NTELV-600 | 120 | 4.0% | |
| Lutron | Diva | DVELV-300P | 120 | 4.0% | |
| Lutron | Maestro | MAELV-600 | 120 | 4.0% | |
| Lutron | Skylark | SELV-300P | 120 | 16.0% | Flicker below 16% |
| Leviton | Illumatech | IPE04-1LZ | 120 | 14.0% | Flicker below 14% |
| Lutron | Maestro | RRD-6NA | 120 | 29.0% | Flicker below 29% |
| Leviton | SureSlide | 6615-POW | 120 | 16.0% | Flicker below 16% |
| Leviton | Decora | DSE06-10Z | 120 | 13.0% | Flicker below 13% |
| Lutron | Caseta | PD-5NE | 120 | 14.0% | Flicker below 14% |
| Lutron | Homeworks | HRD-5NE | 120 | N/A | Flashing at high dimming level |
| Lutron | Homeworks | HQRD-6NA | 120 | 11.0% | Flicker below 11% |
| Leviton | Renoir II | AWSMT-EBW | 120 | 5.0% | |
| Lutron | Grafik-Eye | GRX-3103-A-G | 120 | 4.0% | |
| Forward Phase Dimmers (TRIAC) | | | | | |
| Lutron | Maestro | MAELV-153M-WH | 120 | 10.0% | Flicker below 10% |
| Lutron | Diva | DVCL-153P | 120 | 38.0% | Flicker below 38% |
| Legrand | Adorne Paddle | ADPD453LW2 | 120 | 23.0% | Flicker below 23% |
| Lutron | Ariadni | AYCL-153PH | 120 | 15.0% | Flicker below 15% |
| Lutron | Skylark | SCL-153P-WH | 120 | 10.0% | Flicker below 10% |
| Lutron | Maestro | MA-600-WH | 120 | N/A | Dimmer not responsive |
| Leviton | SureSlide | 6674-POW | 120 | 17.0% | Flicker below 17% |
| Lutron | Caseta | PD-6WCL | 120 | 15.0% | Flicker below 15% |
| Legrand | Harmony | HCL453PW | 120 | N/A | Flashing at high dimming level |
| Legrand | Radiant | RHCL453PW | 120 | N/A | Flashing at high dimming level |

WAC LIGHTING

Responsible Lighting®

Perceived light level percentage is the square root of the measured light level percentage, per IESNA Lighting Handbook. This report reflects WAC's test results of a single fixture in single-pole wiring configuration for reference purposes; actual results may vary based on field conditions. Dimmer manufacturers may modify their product at any time, without notice to WAC Lighting, and therefore WAC Lighting cannot ensure future compatibility. For any questions on this report, please contact WAC Lighting Customer Service at 1-800-526-2588 or sales@wacighting.com.